

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFR-AN6
Release Version	3.1
Release Date	01/20/2025
Previous Version	2.9
Update Category	Recommended
Dependencies	N/A
Important Notes	BIOS Image: BIOS_H12SSFR-1C14_20250120_3.1_STDsp.bin BIOS Update Package: BIOS_H12SSFR-1C14_20250120_3.1_STDsp.zip
Enhancements	1. [Rome] Update AMI Modules based on 5.14_RomeCrb_0ACMK033. Update AGESA RomePI to 1.0.0.K. 2. [Milan] Update AGESA MilanPI to 1.0.0.E based on 5.22_MilanCrb_0ACOU028. Update AGESA MilanPI to 1.0.0.E. 3. [Rome] Update SA50289(TianoCompress Privilege Escalation Vulnerability) to address CVE-119 4. [Rome] Update AMI Modules based on 5.14_RomeCrb_0ACMK034. Update AGESA RomePI to 1.0.0.L. 5. [Milan] Update AMI Modules based on 5.22_MilanCrb_0ACOU029. Update AGESA MilanPI to 1.0.0.F.
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

2.9 (05/29/2024)

1. [Rome][Milan] Update SA50235_Supplement(Extended Image Parser Corruption Vulnerability) to address
 01. BRLY-LOGOFAIL-2023-013(Score 5.1)
 02. BRLY-LOGOFAIL-2023-014(Score 4.4)
 03. BRLY-LOGOFAIL-2023-015(Score 4.4)
 04. BRLY-LOGOFAIL-2023-016(Score 7.5)
 05. BRLY-LOGOFAIL-2023-017(Score 7.5)
 06. BRLY-LOGOFAIL-2023-018(Score 7.5)
 07. BRLY-LOGOFAIL-2023-019(Score 7.5)
 08. BRLY-LOGOFAIL-2023-020(Score 7.5)
 09. BRLY-LOGOFAIL-2023-021(Score 4.1)
 10. BRLY-LOGOFAIL-2023-022(Score 7.5)
 11. BRLY-LOGOFAIL-2023-023(Score 7.5)
 12. BRLY-LOGOFAIL-2023-024(Score 7.5)
2. [Rome][Milan] Update secure boot KEK and DB (Fellow EagleStream SVN 2926).
3. [Rome][Milan] Fix HostInterface On/Off test will drop in 4x times in UEFI Shell.
4. [Rome] Update AMI Modules based on 5.14_RomeCrb_0ACMK029.
5. [Rome] Update AMI Modules based on 5.14_RomeCrb_0ACMK030.
6. [Rome][Milan] Add AMI Resizable BAR support.
7. [Rome][Milan] Enable ASPM in ACPI FACP when pcie ASPM is enabled.
8. [Rome][Milan] Add SMC Debug log support.
9. [Milan] Update AMI Modules based on (BETA)5.22_MilanCrb_0ACOU025.
10. [Milan] Add SMC_OS_PERFORMANCE_ENHANCE item
11. [Rome][Milan] Set Chassis type in smbios to default (0x11) when Chassis type from fru is 0x00 or 0xFF or NULL.
12. [Rome][Milan][Fixes] Automated PXE boot OS install issue.

2.7 (10/30/2023)

1. [Milan] Update Milan B0/B1/B2 stepping CPU microcode and Milan-X B2 stepping CPU microcode for AMD-SB-7005 Security Bulletin to address CVE-2023-20569 issue. B0 Milan microcode 0x0A001079, B1 Milan microcode 0x0A0011D1, B2 Milan-X microcode 0x0A001234. PASS
2. [Milan] Support Supermicro System LockDown feature. PASS
3. [Rome] Update Rome B0 stepping CPU microcode 0x0830107A for AMD-SB-7008 Security Bulletin to address CVE-2023-20593 issue. PASS
4. [Milan][Rome] Add Rocky Linux Boot Option Name. PASS
5. [Milan][Rome] Fixed BMC web can't show LAN MAC address correctly with X710. PASS
6. [Milan][Rome] Fixed that the PCIe Link Width of AOC-SLG4-2H8M2 is downgraded to x4. Warning
7. [Milan][Rome] Restore SMCI secure boot keys and Update Secure Boot DB variable. (Unknown certificate "Addtrust External CA Root" is expired on May 30th 2020).

2.5 (10/12/2022)

1. Update MilanPI to 1.0.0.9 based on 5.22_MilanCrb_0ACOU020.

2. Remove "Vendor Keys" in security page.
3. Modify String naming from SMCI to Supermicro.
4. Update DBX file to fix Secure Boot Bypass issue.
5. Update AGESA RomePI to 1.0.0.E based on 5.14_RomeCrb_0ACMK025.

2.4 (04/22/2022)

1. Configuration backward compatible issue in 01.02.40
2. Wrong Inlet Temp reading on NM command.
3. AMD BH12SSi platform unexpected throttling when enable Smart Power in CMM
4. Update network hostname format
5. The readings style of "Power Consumption" graph should be use radio button.
6. Cannot set the SNMP IP as 0.0.0.0 on X12DGQ-R even though the BMC WEBUI's SNMP destination address setting has already been changed to 0.0.0.0s

2.3 (10/21/2021)

1. [Rome/Milan BIOS] Change BIOS revision to 2.3.
2. [Rome BIOS] Update AGESA RomePI to 1.0.0.C.
3. [Rome BIOS] Exposed Setup item "Enhanced Preferred IO Mode".
4. [Milan BIOS] Update AGESA MilanPI to 1.0.0.6.
5. [Rome/Milan BIOS] Patch BMC Redfish Host Interface was named as ethX when CDN was disabled case under Linux OS.
6. [Rome/Milan BIOS] Disable EFI iSCSI support.
7. [Milan BIOS] Exposed Setup items "BankGroupSwapAlt", "SEV-SNP Support", "Enhanced Preferred IO Mode" and "Root Complex 0x00~0xE0 LCLK Frequency".
8. [Rome/Milan BIOS] According to PM's request, change default of "Wait For "F1" If Error" to Disable.
9. Update Milan B0/B1 stepping CPU microcode and Milan-X B2 stepping CPU microcode to patch Erratum #1381 Processor May Hang When Coherency Probe Hits Instruction Cache Line While Evicted.
B0 Milan microcode 0x0A00104C, B1 Milan microcode 0x0A001143, B2 Milan-X microcode 0x0A001223.

2.2 (9/3/2021)

1. [Rome/Milan BIOS] Change BIOS revision to 2.2.
2. [Rome/Milan BIOS] Add Redfish/SUM Secure Boot feature, update OOB for secure boot and reserve Key.
3. [Rome/Milan BIOS] Support SUM upload/delete HTTPS TLS certificate. (Default Enabled by TOKEN "Sum_UploadTlsKey_SUPPORT")
4. [Rome/Milan BIOS] Per AMD's suggestion, set Relaxed Ordering default to Enabled.
5. [Milan BIOS] Update AGESA MilanPI to 1.0.0.4.
6. [Milan BIOS] Update A010 GN B0 microcode 0A001046.
7. [Rome BIOS] Update AGESA RomePI to 1.0.0.C.
8. [Milan BIOS] Fix SUM cannot modify AMD CBS settings.
9. [Milan BIOS] Fix IPMI Web GUI No Sensor info

2.0 (03/12/2021)

1. [Rome/Milan BIOS] Change BIOS revision to 2.0.
2. [Milan BIOS] Update AGESA MilanPI to 1.0.0.1.
3. [Milan BIOS] Update A011 GN B1 microcode 0A001119.
4. [Rome BIOS] Update AGESA RomePI to 1.0.0.A.
5. [Rome/Milan BIOS] Fix IPV6 disable in the IPMI GUI but BIOS initialize will appear IPV6 address.
6. [Rome/Milan BIOS] Per Platform Management FRU Information Storage Definition v1.1 to enhance SMBIOS Type39 System Power Supply information.
7. According to PM request, disabled NVDIMM support.

1.3 (02/08/2021)

1. Implemented AH25G-m2S2TM Intel X550 Lan Drop recovery scheme
2. Issue 120294, AOC-AH25G-m2S2TM system information incorrect MAC address for 25G

1.0 (12/28/2020)

First release.