

BMC Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X14DBG-DAP
Release Version	01.00.16.00
Build Date	03/14/2025
Previous Version	01.00.13.00
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	None
New features	None
Fixes	<ol style="list-style-type: none">1. Fixed Chassis Assembly was not found.2. X14 10U/4U 3808 related sensor naming.3. [NVSSVT v1.3] BMC 01.00.06.00 — SystemManagement FirmwareInventory fails.4. Fixed hostinterface LinkStatus.5. Fixed EthernetInterface URL Index error in Redfish PCIeDevices NIC page.6. Fixed service validator in RF 1.11.7. Added advance LAN mode support.8. Enhanced error handling to avoid no response when updating parameters with invalid JSON.9. [NVSSVT v1.3] BMC 01.01.06.00 — Telemetry TelemetryPerformanceKPIs fail.10. Added prefix to HGX task resource ID for NVSSVT.

	<ul style="list-style-type: none">11. Filtered the CI-0004 SEL event log.12. Modified redirect can pass resources on bmcweb.13. CPU sensor was red, but the temp was OK.14. HeavyIO Mode FSC Mismatch.15. [NVSSVT v1.3.1] BMC 01.00.13.00 — DMTFCompliance ServiceValidator fails.16. [NVSSVT v1.3.1] BMC 01.00.13.00 — DMTFCompliance InteropValidator fails.17. WebGUI automation test failed.18. [NVSSVT v1.3] BMC 01.00.06.00 — SystemManagement FirmwareInventory fails.19. Fixed bond0 was a random MAC when creating by adding the MACAddr setting to .netdev.20. Fixed Storage service Crash when installing 3808 MR, Storage and GPU sensor missing.21. X14_deltnext Add uboot backup MACAddr method.22. Enhanced MMBI reset mechanism into kernel driver function.23. Added addEventListener: before unload to redirect to logout.
--	--