

# BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

Product Name	X14DBHM
Release Version	1.2
Release Date	03/07/2025
Previous Version	1.0
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	<ol style="list-style-type: none"><li>1. Set AUTO_ACCEPT_PPI to avoid waiting for user acceptance to continue when enabling block SID.</li><li>2. Implemented SmcTpmlInfo module for TPM Redfish MeasurementSet feature.</li><li>3. Updated code base to 5.35_0ACQZ_3544P36_GNRSP_072_8S_BETA.</li><li>4. Updated built-in SuperDiag to ECO candidate 1.10.1 version based on GIT_2cf0c012654e12838a24777224d86a6a3811b034.</li><li>5. Updated Birch Stream Sierra Forest SP PLR2 Candidate - 2025 binaries and Birch Stream Granite Rapids AP - MR1 Candidate BKC - 2025 WW12 binaries.</li><li>6. Enhanced SMC_STYLE_CPU_CORES_ENABLE function by die count.</li><li>7. Added VROC OOB related FDF, Token, and GUID; the default was disabled.</li><li>8. Supported the SMC_STYLE_CPU_CORES_ENABLE function.</li></ol>

	<p>9. Disabled SMC_CORRECTED_MCA_THRESHOLD and filter corrected the error of the processor.</p> <p>10. Corrected processor event information.</p> <p>11. Updated code base to 5.35_0ACQZ_3544P34_GNRSP_071.</p> <p>12. Updated the PN and MAC access method for third-party Intel E810 series.</p>
New features	None
Fixes	<p>1. The attribute 'MaxTDPWatts' could not appear at URI '/redfish/v1/Systems/1/Processors/[number].'</p> <p>2. Fixed the system hang after executing PPR.</p> <p>3. Fixed how there was no PPR event log.</p> <p>4. Fixed how some BIOS items' default value could not be changed.</p>