

## IPMI Firmware

*Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	MBD-X10DSC+-P
<b>Release Version</b>	IPMI Redfish FW 3.63
<b>Release Date</b>	10/25/2017
<b>Previous Version</b>	IPMI Redfish FW 3.25
<b>Update Category</b>	Recommended
<b>Dependencies</b>	None
<b>Important Notes</b>	None
<b>Enhancements</b>	N/A
<b>New features</b>	N/A
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed the following APIs: /redfish/v1/Managers/1/VM1/CfgCD/Actions/IsoConfig.Mount, /redfish/v1/Managers/1/VM1/CfgCD/Actions/IsoConfig.UnMount, and /redfish/v1/Managers/1/IPAccessControl/FilterRule/[rule_num].</li><li>2. Fixed inability to mount 'CD-ROM Image' through web.</li><li>3. Fixed problem of IPMI getting filled with "Invalid Power offset" messages.</li><li>4. Fixed wrong KVM port resulting from 'Sum GetBmcCfg' command.</li><li>5. Fixed issue of missing device ID for sensor AOC_NIC_Temp.</li><li>6. Fixed issue of duplicated sensor information.</li><li>7. Fixed unusual behavior on SNMP page.</li><li>8. Fixed problem of the webpage showing "404-Not Found" when "here" is clicked on Firmware Upload page.</li><li>9. Fixed failure of Patch BitRate in Redfish.</li><li>10. Fixed failure of Patch the DateTime in Redfish.</li><li>11. Fixed inability of sensor alerts to be received by email or SNMP.</li><li>12. Fixed incorrect date and time in Maintenance System Event Log.</li><li>13. Fixed problem of UpdateBMC being done but progress not showing as 100%.</li><li>14. Fixed problem of 'BMC supports OOB BIOS config' showing no support.</li><li>15. Fixed problem of failed DIMM location not matching the motherboard silkscreen.</li></ol>

	<p>16. Fixed issue of some sensors being missing.</p> <p>17. Fixed problem of BMC settings and FRU being lost if BMC updates from 3.16 to 3.55-3.59.</p> <p>18. Fixed Redfish auto test.</p> <p>19. Fixed problem of BMC dying during AC Cycle stress testing.</p>
--	--