

IPMI Firmware

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SSW-F
Release Version	3.64
Release Date	10/2/2017
Previous Version	3.17
Update Category	Recommended
Dependencies	NONE
Important Notes	NONE
Enhancements	1. Hid unused power supply information on power source page.
New features	1. Added support for new fan curve in Thermal Design Guide v4.06. 2. Added support for new Redfish API. 3. Add save button in event log page and system event log page. 4. Added auto refresh to sensor reading page.
Fixes	1. Fixed Redfish auto test. 2. Fixed problem of BMC settings and FRU being lost if BMC updates from 3.16 to 3.55-3.59. 3. Fixed unusual behavior on SNMP page. 4. Fixed problem of the webpage showing "404-Not Found" when "here" is clicked on Firmware Upload page.

	<ul style="list-style-type: none">5. Fixed failure of Patch BitRate in Redfish.6. Fixed failure of Patch the DateTime in Redfish.7. Fixed inability of sensor alerts to be received by email or SNMP.8. Fixed incorrect date and time in Maintenance System Event Log.9. Fixed problem of UpdateBMC being done but progress not showing as 100%.10. Fixed problem of too much margin on sensor reading page and event reading page on high resolution display.11. Fixed abnormal display of syslog.
--	---