

IPMI Firmware

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPU(+)
Release Version	1.39
Release Date	11/17/2017
Previous Version	1.36
Update Category	Recommended
Dependencies	None
Important Notes	N/A
Enhancements	1. Improved the help message descriptions to follow Help Menu Suggestions v1.8. 2. Added support for HII in Redfish.
New Features	1. Fixed problem of help message not matching template. 2. Fixed inability of SUM to run due to invalid DMI information.
Fixes	1. Fixed failure of SUM GetBmcCfg. 2. Removed Upper Critical event log on CPU sensors. 3. Fixed inability of IPMI firmware 1.36 to flash BIOS with SUM. 4. Changed Redfish APIs for Broadcom RAID volumes error from /redfish/v1/Systems/1/Storage/HA-RAID/HA-RAID.[controller_num].Volume.[volume_num] to /redfish/v1/Systems/1/Storage/HA-RAID/Volumes/Controller.[controller_num].Volume.[volume_num].

	5. Fixed problem of IPMI Eject feature not responding.
--	---