IPMI Firmware

Super Micro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Super Micro and the Super Micro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2017 Super Micro Computer, Inc. All rights reserved.

Product Name	X11DPG-QT		
Release Version	1.39		
Release Date	11/17/2017		
Previous Version	1.27		
Update Category	Recommended		
Dependencies	None		
Important Notes	N/A		
Enhancements	1. Improved the help message descriptions to follow Help Menu		
	Suggestions v1.8.		
	2. Adjusted VBAT's low battery threshold from 2.7V to 2.6V for new		
	battery-cell BR2032.		
	3. Removed the scrollbar and moved the buttons to the top.		
New Features	1. Fixed problem of help message not matching template.		
	2. Fixed inability of SUM to run due to invalid DMI information.		
	3. Added support for new thermal guide (SIM_TDG REV. 4.06).		
	4. Added support for Redfish firmware inventory (BIOS/BMC update).		
Fixes	1. Changed Redfish APIs for Broadcom RAID volumes error from		
	/redfish/v1/Systems/1/Storage/HA-RAID/HA-		
	RAID.[controller_num].Volume.[volume_num] to		
	/redfish/v1/Systems/1/Storage/HA-		
	RAID/Volumes/Controller.[controller_num].Volume.[volume_num].		

Project Team Leader	-	Date	
Product Manager		Date	
	8. Fixed ability to enable "LDAP" and "Active I time.	Pirectory" at the same	
	1.35, and failure of fan PWM for SIS_TDG 4.06.7. Fixed problem of server IP being False when disabled.		
	of Standard Speed and Full Speed fan modes being the same for IPMI		
	of fan speed control not working with firmwai	e revision 01.35, problem	
	6. Fixed inability to detect 2x U.2 NVME SSD in	IPMI WebGUI, problem	
	5. Fixed inability of IPMI firmware 1.36 to flash	n BIOS with SUM.	
	4. Removed Upper Critical event log on CPU sensors.		
	3. Fixed failure of SUM GetBmcCfg.		
	2. Fixed failures of battery low threshold and 2.55v.		

Department Head

Date