IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10SRW-F
Release Version	3.0a
Release Date	2/8/2018
Previous Version	2.0b
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	 Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue. Updated BIOS version to 3.0a. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v4.7.0.1014. Updated Intel Server Platform Services 3.1.3.50 for Grantley Refresh Platforms. Removed support for using Ctrl+home to trigger recovery. Changed Memory correctable threshold to 100 and enabled Cloaking for Broadwell CPU E5-26xx SKU. Updated BIOS ACM 3.1.1 PW and SINIT ACM 3.1.1 PW. Added BBS reset function to SmcOobLoadBiosDefault(). Changed tCCD_L Relaxation default to 1 and changed string from Enabled to Auto. Appended VPD - VB tag in VPD-W Tag(0x91) area.
	11. Updated Broadwell-EP RC 4.3.0 PLR11 release.

	12. Added SumBbsSupportFlag into DAT file.
	13. Updated new MRC error log definition.
	14. Added support for JEDEC NVDIMM.
	15. Enabled OA1_SUPPORT to fix inability to modify OEM Data by
	AMIBCP.exe.
	16. Added Intel SPI vulnerability patch for Grantley.
	17. Added "SMBIOS Preservation" Enabled/Disabled item for flash
	recovery.
	1. Displayed setup item "ACS Control" to Enable/Disable PCIe Access
New features	Control Services Extended Capability.
Fixes	2. Implemented SMC Recovery Flash Boot Block feature.
	1. Fixed problem of NVDIMM setup items appearing when optimized
	defaults load even without NVDIMM being installed.
	2. Fixed problem of system resetting or hanging after Watch Dog
	function is enabled during BIOS update.
	3. Fixed inability to get correct Memory CECC DIMM location via SD5.
	4. Fixed problem of system hanging at 79 with some NVDIMMs.