

Notes to Release Notes Authors

- All fields must be completed; please indicate as “N/A” if not applicable.
- Release Notes should document functional changes, dependencies, bug fixes and added features.
- Release Notes must not mention the methods of implementation and/or internal processes.
- Release Notes must not mention of silicon errata and/or other external causations.
- Release Notes must not mention confidential/proprietary information and/or trade secrets of Supermicro or any third party.
- Please delete this page and the signature fields before submitting the document in PDF Format to Marketing for publication.

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10QBL(-CT)/X10QBL-4(CT)
Release Version	3.0b
Release Date	3/1/2018
Previous Version	3.0a
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Changed BIOS revision to 3.0b. 2. Updated BDX-EX RC Package to 3.9.0. 3. Updated Intel BIOS ACM v4.1.0 and SINIT ACM to v4.0.4. 4. Updated Broadwell-EX B-0 stepping microcode to MEF406F1_0B00002A, Haswell-EX E-0 stepping microcode to M80306F4_00000011, and IvyBridge-EX D-1 stepping microcode MED306E7_00000713.
New features	N/A
Fixes	1. Fixed issue of IPMI LAN status being incorrect when using IPMI WebGUI or command to change LAN source. 2. Fixed missing Generic ELOG Protocol. 3. Fixed failure to restore BIOS setting to default when BIOS doesn't

	<p>clear CMOS via IPMI command.</p> <p>4. Fixed corruption of BIOS ACPI table in the Main Block.</p> <p>5. Fixed inability to change OPRAM NVRAM setting with tool.</p> <p>6. Fixed inability of DDD3/DDR4 speed ratio to meet Intel Brickland memory POR.</p> <p>7. Fixed inability of VPD data to find VB tag.</p> <p>8. Fixed inability of system to enter recovery mode when MAIN block is updated and then system powers off.</p>
--	--

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

Product Manager

Date