

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H11DST-B</b>
<b>Release Version</b>	<b>1.0c</b>
<b>Release Date</b>	<b>5/02/2018</b>
<b>Previous Version</b>	<b>1.0b</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>BIOS Image H11DST8.502</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated AGESA NaplesPI to 1.0.0.7 based on AMI CRB_017.</li><li>2. Added support for graphic Early Video mode.</li><li>3. Added support for hidden item "Memory Corrected Error Enabling" to disable OS logs' CECC error.</li><li>4. Added support for NVMe hotplug.</li></ol>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed inability to execute the iSCSI OPROM of Intel x550 LAN card.</li><li>2. Updated AMI PSPDATA region and FV_BB in recovery mode.</li><li>3. Fixed problem of UEFI LAN driver being executed when CSM is disabled and onboard LAN Option ROM Type is Legacy.</li><li>4. Fixed the location of SMCI signature in CMOS.</li><li>5. Fixed failure to preserve SMBIOS types 1 and 2 after flashing BIOS.</li><li>6. Fixed inability to preserve DMI data and some BIOS settings after SUM updates BIOS.</li></ol>

**Release Notes from Previous Release(s)** – these will be appended at the bottom of the current release notes in italic and in smaller print

*1.0b (02/07/2018)*

- 1. Add AOC card support.*
- 2. Add BPN-ADP-6NVMe3-1UB redriver*
- 3. Add Intel X550/X710 linkwidth workaround*
- 4. Revise SIOM information in SMBIOS Type 9*
- 5. Cannot boot to PEX with external LAN card*
- 6. Update AGESA NaplesPI to 1.0.0.5 based on AMI CRB\_014*
- 7. System will stop in recovery mode when updating BIOS from 1.0a to 1.0b*