

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X10DRU-I+</b>
<b>Release Version</b>	<b>3.1</b>
<b>Release Date</b>	<b>6/8/2018</b>
<b>Previous Version</b>	<b>3.0a</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 &amp; CVE-2018-3640) security issue.</li><li>2. Changed BIOS version to 3.1.</li><li>3. Added support for IPMI IPV6.</li><li>4. Removed unsupported memory frequency options from setup menu.</li><li>5. Updated Broadwell-EP RC 4.4.0 release.</li><li>6. Added PCC function.</li></ol>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed problem of Afu /O command clearing SMC SMBIOS region (\$SMC).</li><li>2. Fixed problem of SUM OOB GetSataInfo always showing</li></ol>

	<p><b>"Configuration Type" as "AHCI" when setting "Configure SATA as" to "RAID" or "IDE".</b></p> <p><b>3. Set Descriptor Region of BIOS Region Write Access to "No".</b></p>
--	---

*Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print*

### **3.0a (2/5/2018)**

1. Updated Broadwell-EP RC 4.3.0 PLR11 release.
2. Displayed setup item "ACS Control" to Enable/Disable PCIe Access Control Services Extended Capability.
3. Updated BIOS ACM 3.1.1 PW and SINIT ACM 3.1.1 PW.
4. Added SumBbsSupportFlag into DAT file.
5. Added Intel SPI vulnerability patch for Grantley.
6. Updated Intel Server Platform Services 3.1.3.50 for Grantley Refresh Platforms.
7. Updated CPU microcode to address CVE-2017-5715 security patch issue.
8. Added support for JEDEC NVDIMM.
9. Fixed problem of system resetting or hanging after Watch Dog function is enabled during BIOS update.
10. Fixed problem of MWAIT being disabled on BSP only.
11. Fixed inability to get correct Memory CECC DIMM location via SD5.
12. Fixed inability to log Patrol Scrub UCE.
13. Fixed problem of system hanging at POST 0xA9 when entering setup menu while Intel P4800X uEFI driver is loaded.
14. Fixed problem of microcode update not updating FIT table after using INT15 microcode update tool.
15. Fixed inability of SUM utility get "Setup Prompt Timeout" setup item.