## **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DRFR(-N/NT)
<b>Release Version</b>	3.1a
Release Date	6/21/2018
<b>Previous Version</b>	3.1
<b>Update Category</b>	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	N/A
Fixes	Fixed problem of 1.10 and newer revision boards repeatedly rebooting when trying to update SPS FDT region.

## Release Notes from Previous Release(s)

## 3.1 (6/9/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.
- 2. Added support for IPMI IPV6.
- 3. Removed unsupported memory frequency options from setup menu.
- 4. Disabled Cloaking for Broadwell E5-2687W V4 CPU (W: workstation SKU).
- 5. Updated Broadwell-EP RC 4.4.0 release.
- 6. Fixed problem of Afu /O command clearing SMC SMBIOS region (\$SMC).
- 7. Fixed problem of SUM OOB GetSataInfo always showing "Configuration Type" as "AHCI" when setting "Configure SATA as" to "RAID" or "IDE".
- 8. Fixed inability to enter setup menu by pressing "DEL" key if Re-try Boot feature is enabled and there are no boot devices.
- 9. Set Descriptor Region of BIOS Region Write Access to "No".