

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X11SPL-F</b>
<b>Release Version</b>	<b>2.1</b>
<b>Release Date</b>	<b>6/14/2018</b>
<b>Previous Version</b>	<b>2.0b</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 &amp; CVE-2018-3640) security issue.</li><li>2. Changed BIOS revision to 2.1.</li><li>3. Updated 5.12_PurleyCrb_0ACFD088 for Purley Skylake platform PLR7, BKC 2018 WW20.</li><li>4. Updated BIOS ACM 1.3.7 and SINIT ACM 1.3.4.</li><li>5. Added one event log to record that the event log is full.</li><li>6. Added support for VMD settings to be preserved after flashing.</li><li>7. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v5.4.0.1039.</li><li>8. Added BIOS/ME downgrade check for SPS 4.0.4.340.</li><li>9. Added support for UEFI mode PXE boot of F12 hot key Net boot.</li><li>10. Added setup item "SmcBusMasterEn" for enabling Parent bridge of the devices in the gSmcPciForceEnableBusMasterList.</li><li>11. Corrected BIOS/ME downgrade check for SPS 4.0.4.340.</li></ol>

	<b>12. Added support for SATA FLR with enabled as default.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Fixed problem of DMI being cleared when running SUM UpdateBios. 2. Fixed problem of Ctrl + Alt + Del causing system to hang after flashing BIOS. 3. Fixed missing SMBIOS Type40 information if LAN 2 is on board.</b>

**Release Notes from Previous Release(s)**

**2.0b (2/26/2018)**

1. Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue.
2. Changed BIOS revision to 2.0b.
3. Updated 5.12\_PurleyCrb\_0ACFD085Beta for Purley Skylake platform PLR 4, BKC WW02.
4. Fixed inability to reset the system under DOS by pressing "Ctrl-Alt-Del" on USB keyboard when "Port 60/64 Emulation" is disabled.
5. Fixed problem of SMC skipping first boot option in UEFI mode when retrying boot.
6. Displayed setup item "ACS Control" to Enable/Disable PCIe Access Control Services Extended Capability, with Enabled as default.
7. Disabled CPU2 IIO PCIe root port ACPI hot plug function.
8. Fixed issue with IPMI force boot.
9. Fixed malfunction of "SMBIOS Preservation" Disabled.
10. Fixed inability of some CPUs to display correct microcode revision under BIOS setup menu.