# **IPMI Firmware / BIOS Release Notes Form**

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Dun dunt Name	V44DDC DE
Product Name	X11DPS-RE
Release Version	3.1 SPS: 4.1.4.296
Release Date	6/11/2019
Previous Version	3.0a
<b>Update Category</b>	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Skylake H0/M0/U0 CPU μ-code to version 5E and Cascade
	Lake B0/B1 to version 24.
	2. Updated Intel® VROC package to version 6.1.1.1011.
	3. Updated RC0584.D01.
	4. Set ADDDC to enabled by default.
New features	N/A
Fixes	N/A

#### Release Notes from Previous Release(s)

### 3.0a (4/2/2019)

- 1. Added support for Purley Refresh platform.
- 2. Updated Skylake H0/M0/U0 CPU microcode to version 57.
- 3. Updated Intel® RSTe package to version 6.0.0.1024.
- 4. Set NVDIMM ADR timeout to 600μs.
- 1. Added ME Jumpless Recovery Feature.

## 2.1a (10/3/2018)

- 1. Updated the RSTe revision to 5.5.0.1028.
- 2. Enhanced the BIOS secure flash upgrade feature (firmware signature).
- 3. Fixed the 50-second delay when booting into UEFI shell, DOS, and various Operating Systems (OS).
- 4. Fixed DMI writing error with full memory DIMM and ruler NVMe SSD plugged in.

#### 2.1 (7/18/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.
- 2. Enabled BIOS secure flash upgrade feature (firmware signature).
- 3. Added security signature feature for IPMI BIOS Upgrade.
- 4. Implemented RSD feature.
- 5. Fixed inability of system to detect SATA device when the PCH is very hot.