IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X11SPM-F/T(P)F
Release Version	3.2
Release Date	10/18/2019
Build Date	10/18/2019
Previous Version	3.1
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Changed BIOS version to 3.2.
	2. Updated Cascade Lake-SP CPU microcode and Skylake-SP
	microcode.
	3. Updated Cascade Lake-SP A0 stepping CPU microcode.
	4. Updated AMI label 5.14_PurleyCrb_0ACLA049_BETA for BKC
	WW36 IPU 2019.2 and AMI security update SA50072.
	5. Updated SPS_E5_04.01.04.339.0 from BKC WW36 IPU 2019.2 to
	address PSIRT-TA-201905-011.
	6. Updated SINIT/BIOS ACM from BKC WW36 IPU 2019.2 to address
	CVE-2019-0151 and CVE-2019-0152.
	7. Updated SATA/sSATA RAID OPROM/EFI driver to VROC PreOS
	v6.2.0.1034 PC.
	8. Enhanced F12 hot key PXE boot feature.

	9. Added a mechanism to show warning message and shut down
	system if a CPU TDP over specifications is installed.
	10. Updated the behavior for the feature that updates SMBIOS Type 1
	and 3 with FRUO.
	11. Added Redfish/SUM Secure Boot feature to update OOB for
	secure boot and reserve Key.
	12. Displayed Setup item "ARI Support".
	13. Added setup item to control 16Gb based Single Die Package
	DIMM tRFC optimization.
	14. Added back erase NVDIMM routine.
	15. Updated VBIOS and VGA EFI Driver to 1.10.
	16. Disabled ADDDC/SDDC and set PPR as hPPR.
New features	1. Added Enhanced PPR function and set disabled as default.
	1. Fixed problem of key details showing "Security Violation" after
	loading Factory secure boot keys.
	2. Fixed problem of two OS (Redhat & Ubuntu) boot devices
	appearing in boot order.
Fixes	3. Fixed failure of OPROM control item if CSM is disabled.
	4. Corrected display of the IPMI AUX revision.
	5. Removed PXE option for "OnBoard LanX Option ROM" when "Boot
	mode select" is UEFI.
	6. Changed OOB download and Upload Bios Configuration sequence.
<u> </u>	I .

3.1 (5/21/2019)

- 1. Changed BIOS version to 3.1.
- 2. Updated Skylake-SP/Cascade Lake-SP CPU microcode.
- 3. Updated Intel BKCWW16 2019 PV PLR1.
- 4. Updated SPS E5 04.01.04.296.0 from BKC WW16 2019.
- 5. Updated SATA/sSATA RAID OPROM/EFI driver to VROC PreOS v6.1.0.1017.
- 6. Updated EIP467272 for AMI SA50069, SA50070.
- 7. Set SDDC Plus One or SDDC to disabled by default.
- 8. Set ADDDC to enabled by default.
- 9. Fixed inability to change IPv6 address or IPv6 Router1 IP address.

3.0c (3/27/2019)

- 1. Updated SPS E5 04.01.04.296.0 from BKC WW16 2019.1. Changed BIOS version to 3.0c.
- 2. Updated CPU microcode version to MB50656_04000021 for Cascade Lake-SP B0 CPUs.
- 3. Updated CPU microcode version to MB50657 05000021 for Cascade Lake-SP B1 CPUs.
- 4. Updated AMI label 5.14 PurleyCrb OACLA044 BETA for BKC WW10 2019.
- 5. Updated to SPS 4.0.04.381 or above for INTEL-SA-00213 Security Advisory.
- 6. Added temporary fix for SKX (CLX) 4114 CPU Memory Training Error with Micron (18ASF2G72PDZ-2G6E1) RDIMM.
- 7. Fixed failure to boot into VMare OS when set to Maximum Performance, even if Monitor/MWAIT is enabled.
- 8. Fixed incorrect Bus Number and Device/Function Number of the SMBIOS Type 41 for onboard LANs.
- 9. Fixed inability of BMC to access chassis information.

3.0b (3/04/2019)

- 1. Changed BIOS version to 3.0b.
- 2. Added support for Purley Refresh platform.
- 3. Updated to SPS 4.1.02.174 or above for INTEL-SA-00185 Security Advisory and RC 549.D13 or above for INTEL-SA-00192 Security Advisory.
- 4. Updated CPU microcode MB750654_0200005A for Skylake-SP H0/M0/U0 stepping CPUs.
- 5. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v6.0.0.1024.
- 6. Added support for Monitor Mwait feature.
- 7. Fixed inability of VMD status to load default if loading default by AFU.
- 8. Added support for SMC HttpBoot.
- 9. Added support for RFC4122 UUID format feature to set RFC4122 encoding from build time produced by IPMICFG 1.29 tool or newer.
- 10. Set PCIe correctable and uncorrectable (non-fatal) error report to disabled by default.
- 11. Disabled unused SPS ME "CUPS IIO" and "Volumetric Airflow" sensor.
- 12. Set NVDIMM ADR timeout to 600us.
- 13. Enhanced the solution for the error/warning message from dmidecode after a modification by AMIDE.
- 14. Prevented inability to update BIOS when CMOS 51 value is 0x0a or 0x1a.
- 15. Fixed problem of BIOS always retrying boot when Re-Try Boot is Disabled.
- 16. Fixed malfunction of support for LEGACY to EFI.
- 17. Fixed failure of Always Turbo in Linux kernel 7.x.
- 18. Fixed malfunction of CPU PBF (Prioritized Base Frequency).
- Fixed incorrect PBF high frequency core number when Hyper-Threading is disabled.

- 20. Modified UEFI network description to IPv4/IPv6 to follow Industry Standard.
- 21. Fixed issue of no AOC SAS Temp when AOC-S3108L-H8iR is installed.

2.1 (6/15/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639 & CVE-2018-3640) security issue.
- 2. Changed BIOS revision to 2.1.
- 3. Updated 5.12 PurleyCrb 0ACFD088 for Purley Skylake platform PLR7, BKC 2018 WW20.
- 4. Updated BIOS ACM 1.3.7 and SINIT ACM 1.3.4.
- 5. Added one event log to record that the event log is full.
- 6. Added support for VMD settings to be preserved after flashing.
- 7. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v5.4.0.1039.
- 8. Corrected BIOS/ME downgrade check for SPS 4.0.4.340.
- 9. Added support for UEFI mode PXE boot of F12 hot key Net boot.
- 10. Added setup item "SmcBusMasterEn" for enabling Parent bridge of the devices in the gSmcPciForceEnableBusMasterList.
- 11. Added support for SATA FLR.
- 12. Fixed problem of DMI being cleared when running SUM UpdateBios.
- 13. Fixed problem of Ctrl + Alt + Del causing system to hang after flashing BIOS.

2.0b (2/26/2018)

- 1. Updated CPU microcode to address 'Spectre' variant 2 (CVE 2017-5715) security issue.
- 2. Updated BIOS version to 2.0b.
- 3. Updated 5.12_PurleyCrb_0ACFD085Beta for Purley Skylake platform PLR 4, BKC WW02.
- 4. Displayed setup item "ACS Control" to Enable/Disable PCIe Access Control Services Extended Capability, with Enabled as default.
- 5. Disabled CPU2 IIO PCIe root port ACPI hot plug function.
- 6. Fixed issue with IPMI force boot.
- 7. Fixed malfunction of "SMBIOS Preservation" Disabled.
- 8. Fixed problem of SMC skipping first boot option in UEFI mode when retrying boot.
- 9. Fixed inability to reset the system under DOS by pressing "Ctrl-Alt-Del" on USB keyboard when "Port 60/64 Emulation" is disabled.
- 10. Fixed inability of some CPUs to display correct microcode revision under BIOS setup menu.
- 11. Fixed inability to detect 2 NVMes with AOC 2E2T.
- 12. Fixed failure of SUM TC 219.