BMC Firmware Release Notes

Product Name	**B14DBT**
Release Version	01.00.21.31
Build Date	01/20/2025
Previous Version	01.00.21.20
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**None**
New features	1. **Cooling page Advanced Settings options.**
Fixes	1. **The option of Auto reset system after CPU CATERR/IERR interrupt happens should be kept on the ON status in Operator permission.** 2. **The description of [MEL-0072] do not match the spec.** 3. **Failed to receive SNMP trap for [IPMI-9036] and [IPMI-9040].** 4. **SAA [Attestation] Generated measurement file failed.** 5. **OemDumpService.Collect failed due to return code is 400, but should be 403.** 6. **Redfish — Check Operator Privilege fail on /Actions/OemDumpService.Collect.**

7. Operator Permission Privilege SYSTEMCRASHDUMP - AUTO_RESET_SYSTEM_SWITCH is not Enabled.

8. POST requested to collect dump failed via Operator role.

9. Redfish Automation Operator Privilege Failure.

10. BMC should support a maximum of four KVM sessions.

11. During AC on-off cycles may result in incorrect date/time.

12. Dynamic DNS cannot Access Hostname with Dynamic Update Enabled.

13. User privilege is not able to see Full Info on Power page.

14. Syslog packet doesn't match the correct format. Showed '\n' at the end.

15. Web Function — Date and Time should be read only.

16. Enable Date and Time write permission.

17. CPU sensor errors with one CPU installed

18. The threshold of RTX 2000 ADA should be 95°C and not 90°C.

19. ALVEO V80 senser reading is missing.

20. The time for the event logs is incorrect.

21. Redfish should not show CUPSMetrics if the CPU does not support it.

22. Four Bytes BMC version support for CMM-6.

23. Storage page Button Blink/Unblink, Eject/Insert, Erase/Abort, and Make/Remove Hotsparemerge.

24. License still shows up after deletion thru inband, but outband check it shows "0."