**IPMI Release Notes**

| | |
|---|---|
| **Product Name** | **X12SPi-TF** |
| **Release Version** | **01.00.21** |
| **Build Date** | **10/22/2021** |
| **Previous Version** | **01.00.18** |
| **Update Category** | **Critical** |
| **Dependencies** | **None** |
| **Important Notes** | **None** |
| **Enhancements** | **1. Improved compatibility with Redfish ATT after applying the security patches.** <br><br> **2. Set fan speed to maintain during BMC fwUP and BMC reset.** |
| **New features** | **N/A** |
| **Fixes** | **1. Fixed broken SUM inband feature.** <br><br> **2. Disabled creation and activation of a null user and password.** <br><br> **3. Fixed problem of BMC crashing and restart being forced due to malicious data transmission.** <br><br> **4. Fixed problem of NTP showing failure message after setting.** <br><br> **5. Fixed mismatch of TEE OS 0x42 error message on IPMI MEL and "Kernel code segment (offset: ##) was compromised."** <br><br> **6. Fixed issue of system with AST2600 hanging when running DC on/off testing with Red Hat 8.3.** |