BMC Firmware Release Notes Form

Product Name	**X12DPFR-AN6**
Release Version	**1.00.21**
Build Date	**11/22/2021**
Previous Version	**1.00.17**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	1. **Better compatibility with redfish ATT.** 2. **Now supports the new group sensor design.**
New features	**None**
Fixes	1. **Fixed hang issue when running DC On/Off test with Red Hat Linux 8.3.** 2. **Fresh page added after "enable/disable ports".** 3. **Fixed the Supermicro Update Manager (SUM) to enable inband BIOS updates.** 4. **Creation and activation of a null user and password is no longer possible.** 5. **Fixed BMC crash and forceful restart caused by malicious data transmissions.**

	6. Fixed bug that retains data in resolve.conf even after the BMC has been reset to factory defaults. 7. NTP no longer shows a fail message after setting. 8. The "TEE OS 0x42" error message on the IPMI MEL now matches with "Kernel Code segment (offset:###) was compromised". 9. Fixed the MultiNode attribute issue. 10. During a cpld firmware update, if the system is off, the BMC will now power on the system. 11. Fixed issue where JAVA iKVM can't initiate under Windows Server OS.