IPMI Firmware Release Notes Form

Product Name	**H12DSi-N6/NT6**
Release Version	**1.01.13**
Release Date	**4/27/2022**
Previous Version	**1.00.26**
Update Category	**Recommended**
Dependencies	**BIOS 2.4**
Important Notes	**IPMI Image:** **BMC_H12AST2600-ROT-E201MS_20220427_01.01.13_STDsp.bin** **IPMI Update Package:** **BMC_H12AST2600-ROT-E201MS_20220427_01.01.13_STDsp.ZIP**
Enhancements	**N/A**
New features	**N/A**
Fixes	1. **Fixed: After inserting a S3916 RAID card, there is no event log generated, however IPMI dashboard is healthy but shows red.** 2. **Fixed: H12DSI-N6 => P2_VMEMABCD/P2_VMEMEFGH Sensor bug.** 3. **Set IPV6 factory default to 'enabled'.**

1.00.26 (10/05/2021)

1. Corrected Memory FSC on MBD-H12DSI-N6-P.
2. Corrected CPU FSC on MBD_H12DSI-N6 for optimal and Heavy IO.

1.00.23 (6/17/2021)

1. Added support for Aspeed2600 chip A3.

1.00.19 (4/13/2021)

 Initial Release