BMC Firmware Release Notes

Product Name	**X12STL-F_IF**
Release Version	**1.13.04**
Build Date	**6/27/2022**
Previous Version	**0.13.20**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**None**
New features	**None**
Fixes	1. **Fixed redfish login checking issue when input password shorter than real one but all correct** 2. **Added Chassis workaround for Tatlow platform** 3. **Reloading IPMI Configuration will lose SMTP sender address.** 4. **IPMI ECO automation test failure.** 5. **Anonymous account or null value can be created on X11 and X12. Buffer overflow in ipmi_lan ASF protocol. resolv.conf can't be deleted, it may cause a potentially DNS Hijacking.** 6. **Test case 373 - In-Band - Test "Change LAN via BMC configuration" failure. SUM test case 373 failure. Test case**

	373 - In-Band - Test "Change LAN via BMC configuration" fail, due to BMC LAN cannot be modified. 7. **3808/3908 card feature(master ranch).**