BMC Firmware Release Notes Form

Product Name	**X13DEG-M**
Release Version	**1.01.08**
Build Date	**4/18/2024**
Previous Version	**1.01.04**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	• **SMC-2024010010 Command Injection attack.** • **SMC-2024010011 XSS attack.** • **(CVE-2023-33413) SMC-2024010012 Command Injection attack.**

Enhancements	1. **a.) Adjusted fan curve: NVMe, Retimer, AOC NIC.**
	   b.) Supports BF3 transceiver.
	   c.) Supported AOM-GP401-SW to update CPLD.
	2. **a.) Adjusted fan curve: GPU, HBM, NVSwitch.**
	3. **a.) Updated TEE.**

New features	1. **a.) Supports AMD MI300 GPU.**

Fixes	1. BMC WEB Dashboard does not display all IPv6 addresses in the IPv6 Address list if more than 6 addresses are configured.
	2. [SSM_5.5.0_b1222] The system Information test fail (Processor:lack of current clock speed,Network:lack of LAN info and LAN name is same) on the X13DEG-M.
	3. [ECO] X13DEG BF3 kept triggering temperature going low event log. [174290] [ECO_SYS-421GE-TNHR2-LCC] The BMC will show error log. [IPMI-1002] AOC_PORT1 Temp, Lower Critical - going low - Assertion when DC cycle.
	4. Automation TC2060: OOB - Test "GetCpldInfo" and "UpdateCpld" failed. [171785] [IPMI ECO v.01.02.02] Automation tests Failure/.
	5. Web Function – Extra '[MEL-0131] iKVM was launched successfully' after iKVM resetting. [167927] Launch 4 JAVA iKVM sessions, reset iKVM, sessions are not disconnected, and unknown users show in User List. [163486] Incorrect iKVM reset error code when opening more than 2-3 sessions. (code: 12592, reason: 01) etc...
	6. a.) Fixed FAN4 missing issue.