BMC Firmware Release Notes Form

Product Name	**X13DEG-M**
Release Version	**1.01.10**
Build Date	**5/7/2024**
Previous Version	**1.01.08**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	• **SMC-2024010010 Command Injection attack** • **SMC-2024010011 XSS attack** • **(CVE-2023-33413) SMC-2024010012 Command Injection attack**
Enhancements	1. **Added OEM command to disable/enable leakage detection.** **cmd: 0x30 0x68 0x3a** **para:** **[byte 1] Action: 0:Get, 1: Set** **[byte 2] Option: 0: Leakage Detection** **[byte 3] 0: Disable 1: Enable** 2. **a.) Adjusted fan curve: GPU, HBM, NVSwitch.** 3. **a.) Adjusted fan curve: NVMe, Retimer, AOC NIC.** **b.) Support BF3 transceiver.** **c.) Support AOM-GP401-SW to update CPLD.** 4. **a.) Updated TEE.**

New features	None
Fixes	1. Web Function – Extra '[MEL-0131] iKVM was launched successfully' after iKVM resetting. Launched four JAVA iKVM sessions, reset iKVM, sessions are not disconnected, and unknown users show in User List. Incorrect iKVM reset error code when opening more than 2-3 sessions. (code: 12592, reason: 01) etc... 2. a.) Fixed FAN4 missing issue. 3. Automation TC2060: OOB – Test "GetCpldInfo" and "UpdateCpld" failed. [IPMI ECO v.01.02.02] Automation tests Failure. 4. [ECO] X13DEG BF3 kept triggering temperature going low event log. [ECO_SYS-421GE-TNHR2-LCC] The BMC will show error log. [IPMI-1002] AOC_PORT1 Temp, Lower Critical – going low – Assertion when DC cycle. 5. BMC WEB Dashboard does not display all IPv6 addresses in the IPv6 Address list if more than 6 addresses are configured.