IPMI Firmware Release Notes Form

Product Name	**G1SMH**
Release Version	**01.02.26**
Build Date	**03/15/2024**
Previous Version	**01.02.15**
Update Category	**Recommended**
Dependencies	**BIOS R1.1a**
Important Notes	**IPMI Image:** **BMC_SCMAST2600-ROT20-2501MS_20240315_01.02.26_STD.bin IPMI Update Package:** **BMC_SCMAST2600-ROT20-2501MS_20240315_01.02.26_STD.zip** **Note:** **IPMI firmware can be updated via WebGUI or SUM tool.**
Enhancements	**1.**
New Features	**N/A**
Fixes	**1. NVSSVT v0.7 TelemetryOOB failures for CG1** **2. NVSSVT resiliency BMCCore missing log services** **3. Fail to unmount ISO image** **4. All sensors went N/A during DC ONOFF**

Release Notes from Previous Release(s)

01.02.06 (12/13/2023)
Initial Release

01.02.15 (01/25/2024)

1. NCSI re-scan and switch were treated as "Failover" during PWRON/PWROFF
2. Fixed the issue where ipmitool commands failed to properly route IPv6 addresses configured with SLAAC and DHCPv6.
3. Fixed the issue where power consumption graphs sometimes appeared incorrect.
4. Fixed the issue where the Redfish service validator failed.