IPMI Firmware Release Notes Form

Product Name	**H14DSH**
Release Version	**01.00.03.00**
Build Date	**09/23/2024**
Previous Version	**00.00.19.00**
Update Category	**Recommended**
Dependencies	**BIOS V1.1**
Important Notes	**BMC_H14AST2600-ROT-9501MS_20240923_01.00.03.00_STDsp.bin - IPMI Image** **BMC_H14AST2600-ROT-9501MS_20240923_01.00.03.00_STDsp.zip - IPMI image and flash utility package**
Enhancements	**N/A**
New features	**N/A**
Fixes	1. **The CPU cooling zone operates at full speed to prevent CPU damage in case of a temperature exception- CPU temperature showing up NA/0 degree.** 2. **The restored BIOS warning message does not match the specification as defined.** 3. **After NVMe is ejected via webUI , it cannot be inserted back again . No NVMe drive is selectable.** 4. **Fixed owner privilege to support CPLD force update from X13 to X14**

Release Notes from Previous Release(s)

00.00.19.00 (07/11/2024)

First release.