IPMI Firmware Release Notes Form

Product Name	**H14SHM**
Release Version	**01.01.00.03**
Build Date	**03/07/2025**
Previous Version	**01.00.08.00**
Update Category	**Recommended**
Dependencies	**BIOS 1.3**
Important Notes	**IPMI image: BMC_H14AST2600-ROT-9601MS_20250307_01.01.00.03_STDsp.bin** **IPMI Update package: BMC_H14AST2600-ROT-9601MS_20250307_01.01.00.03_STDsp.zip**
Enhancements	**N/A**
New features	**N/A**
Fixes	**1. No Network AOC in System Info and Component Health in SSM.** **2. Fixed issue where BMC doesn't generate RAS function event log** **3. Fixed issue where AIOM_NIC1 senser is not in sensors page.** **4. Fixed issue where NVMe Storage capacity is not contained in redfish in SCC.** **5. Fixed issue where Notifications can't be preserved in SCC after updating BMC via WebUI.** **6. Fixed issue of WebUI Network page abnormal.** **7. Fixed issue where BMC sensor readings show an abnormal item "AIOM_Port1 Temp".** **8. Fixed issue where hostname default value in Web Function doesn't match the specification.** **9. Fixed issue where hostname in Web function is not reflected in server identification after saving.**

	10. Fixed issue where modifying SNMP community strings causes a connection error.
	11. Fixed issue where modify alert window does not close automatically after navigating to license activation page.
	12. Fixed issue where MEL entry triggered after BMC reset does not align with SPEC.
	13. Fixed issue where error message and unintended MEL triggered after changing LAN interface.
	14. Fixed issue where invalid BMC hostname for DDNS displays incorrect error message.
	15. Fixed issue where unexpected error and logout after enabling SNMPv2 community string show mode.
	16. Fixed incorrect error messages for unsupported IPv6 addresses
	17. Fixed issue where serial number and part number are blank after changing FRU.
	18. Fixed issue where fails to change LAN via BMC configuration.
	19. Fixed issue where link status is not "null" in Redfish ethernet interfaces of SCC when AOC-AG-i2M does not support PLDM.
	20. Fixed issue of failed to deploy OS in SSM.
	21. Fixed issue of CPU OEM_TYPE_USB / OEM_TYPE_SATA fail.
	22. Fixed issue where SuperDiag by SAA run Fail under H14SHM.
	23. Fixed issue of system diagnostics fail.
	24. Fixed issue where UID shows "off" under BMC web after turning on the UID via SCC.
	25. Fixed issue where sensors monitor fail.
	26. Fixed issue where sends Redfish test event failure.
	27. Fixed issue where FAN speed and control setting function fail.
	28. Fixed issue where MEL log cannot be generated.
	29. Fixed issue where leakage de-assertion event log can't be observed.
	30. Fixed issue where RAID volume created via BMC UI cannot be deleted.
	31. Fixed issue where gateway IP lost in BIOS.
	32. Fixed FAN location issue.
	33. Fixed issue where BMC sensor readings for the CPU and DIMM became unavailable during power on-off.

Release Notes from Previous Release(s)

01.00.08.00 (12/18/2024)
First release.