IPMI Firmware / BIOS Release Notes Form

Product Name	X11DPL-i-P (All)
Release Version	2.0
Release Date	12/4/2017
Previous Version	1.0a
Update Category	BIOS Update
Dependencies	N/A
Important Notes	ECO #20055 BIOS Image X11DPLI_7.B29
Enhancements	1. Changed BIOS revision to 2.0. 2. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v5.3.0.1052. 3. Updated BIOS ACM 1.3.4. 4. Update SPS to 4.0.4.294. 5. Updated CPU microcode SRV_P_214 for Skylake-EP H0/M0/U0 stepping CPUs. 6. Updated 5.12_PurleyCrb_0ACFD084_BETA for Purley Skylake platform PLR 3.1
New features	N/A
Fixes	1. Fixed problem of SNC being disabled once NVDIMM is present in system. 2. Fixed problem of DMI being cleared when SUM LoadDefaultBiosCfg is run.

Release Notes from Previous Release(s) – *these will be appended at the bottom of the current release notes in italic and in smaller print*

N/A

_____   _____
Product Manager   *Date*

_____   _____
Project Team Leader   *Date*

_____   _____
Department Head   *Date*