IPMI Firmware / BIOS Release Notes Form

Product Name	**X11DPH-I/T/TQ**
Release Version	2.0
Release Date	11/30/2017
Previous Version	1.0
Update Category	Critical
Dependencies	None
Important Notes	N/A
Enhancements	1. Updated SATA RAID OPROM/EFI driver to RSTe PreOS v5.3.0.1052. 2. Updated the onboard X722 Lan NVM to 722PAD1C. 3. Reduced the boot time caused by IPv4/IPv6 polling. 4. Updated BIOS ACM 1.3.4. 5. Added support for AOC-SLG3-2M2 rev. 1.00 AOC cards (M.2 Riser Card). 6. Updated SPS 4.00.04.294 PLR 3.1 PV version. 7. Updated CPU microcode SRV_P_214 for Skylake-EP H0/M0/U0 stepping CPUs. 8. Updated 5.12_PurleyCrb_0ACFD084_BETA for Purley Skylake platform PLR 3.1.
New features	N/A

Fixes	1. Fixed failure of the IIO Root port PCIe manual bifurcation.
	2. Fixed problem of system rebooting endlessly when equipping dTPM module.
	3. Fixed problem of DMI being cleared when running SUM LoadDefaultBiosCfg.