IPMI Firmware

Product Name	**X11DPG-OT-CPU**
Release Version	**1.52**
Release Date	**5/03/2018**
Previous Version	**1.45**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**None**
New features	**1. Revised Redfish firmware inventory (BIOS/BMC update) (Redfish _API_full_list_2018_03_16.xlsx).** **2. Added Redfish features for downloading/updating IPMI configuration (Redfish _API_full_list_2018_03_16.xlsx).** **3. Revised Redfish actions for clearing the event log (Redfish _API_full_list_2018_03_16.xlsx).** **4. Enabled the AC power on event log.** **5. Added Redfish memory information feature.**
Fixes	**1. Fixed Redfish auto test fail.** **2. Fixed AC power on event log being reported upon cold reboot.** **3. Fixed no Processor Automatically Throttled event when CPU**

	overheats.
	4. Fixed changing of UTC time zone via SMCIPMITOOL commands.
	5. Removed FPGA VRM temperature sensor monitoring.
	6. Fixed IPMI 1.45 returning wrong power reading in SPM after updating to IPMI 1.45. Fixed incorrect power reading on the "power consumption": total AVG power on SPM does not fluctuate with CPU power consumption.

_____   _____

Product Manager   *Date*