IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	**K1SPI(-T)**
Release Version	**1.48**
Release Date	**6/15/2018**
Previous Version	**1.43**
Update Category	**Recommended**
Dependencies	**N/A**
Important Notes	**N/A**
Enhancements	**N/A**
New features	**1. Added Redfish memory information feature.**
Fixes	**1. Added workaround for failure of SUM test.** **2. Fixed failure of Redfish automation tool check test.** **3. Fixed problem of the help page of iKVM/HTML5 console not supporting multi-language content and only supporting English.** **4. Fixed failure of 12 critical Redfish automation tests.** **5. Fixed missing SEL log entry and buzzer during overheat test.** **6. Fixed timeout of Invalid Default Active Directory.** **7. Fixed failure of Redfish automation test.**

Release Notes from Previous Release(s)

1.43 (12/6/2017)

1. Renamed Redfish APIs as follows: from /redfish/v1/UpdateService/SSL to /redfish/v1/UpdateService/SSLCert, and from /redfish/v1/UpdateService/SSL/Actions/SSL.Upload to /redfish/v1/UpdateService/SSLCert/Actions/SSLCert.Upload.
2. Changed the license requirement of WebGUI syslog from DCMS to OOB.
3. Improved multi-language content on the iKVM/HTML5 option menu and submenu.
4. Added 204 and 405 http status code support for Redfish API so that 204 http status code responds to APIs that support PATCH and 405 http status code responds to APIs that do not support PATCH.
5. Nested ICANN domain in "OEM" part if there is data to show.
6. Fixed inability of DCMS mods to enable Syslog function and ability to read Syslog without OOB key.
7. Added workaround for PCH.
8. Fixed problem with webpage login.