IPMI Firmware / BIOS Release Notes Form

Product Name	**X11DGO-T**
Release Version	**1.14**
Release Date	**9/17/2018**
Previous Version	**1.12**
Update Category	**Recommended**
Dependencies	**None**
Important Notes	**None**
Enhancements	**1. Improved scanning power supply FRU information process.**
New features	**N/A**
Fixes	**1. Fixed incorrect Input/Output PWR high limit threshold.** **2. Added software workaround for GPU node issue.**

1.12 (5/23/2018)

1. Fixed problem of 0 Watt power consumption being included in power consumption history.

2. Fixed issue of FAN2 RPM showing 0 RPM on IPMI Web's power source page.

3. Fixed incorrect PLX fan curve.

4. Fixed incorrect GPU fan curve.

5. Fixed problem of fan RPM fluctuating when the GPUs are stressed.

6. Fixed problem of fan failure triggering no event log or front panel LED.