

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H11SSL-i/C/NC (All)
Release Version	1.52.0
Release Date	11/18/2019
Previous Version	1.46
Update Category	Critical
Dependencies	N/A
Important Notes	ECO #23131 IPMI Image SMT_H11AST2500_32M_152_0.bin Please update IPMI with attached Flash Utility in package.
Enhancements	[Unique password] Improved ADMIN password is incorrect after reloading IPMI configuration
New features	1. BMC FW solution to program and store unique pre-programmed password. 2. Display advanced power readings through DCMI (Data Center Management Interface) for AMD platforms
Fixes	1. Fixed PBID#103088 System will not have any screen after flashing BIOS 2. Fixed PBID#100467 Issues on SPM REST API 3. Fixed PBID#103149 There is no relevant log when CPU Temperature has increased and meet the 95 degrees threshold [Critical Upper Limit (Red Color)] 4. Fixed the CPU throttled would occur when running Linpack with ROME CPU. 5. Fixed the SOL window cannot launch.

Release Notes from Previous Release(s) – these will be appended at the bottom of the current release notes in italic and in smaller print

Revision 1.38 (2019/09/06)

First release.

Product Manager

Date