

IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X10DSN-TS
Release Version	3.77
Release Date	12/19/2019
Previous Version	1.18
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Patched CVE-2019-6260.
New features	1. Added BMC firmware solution to program and store unique pre-programmed password.
Fixes	1. Fixed problem of fans reaching full speed when other node is off or absent. 2. Fixed missing VPD _HGST HUSMR7676BDP3Y1. 4. Fixed inability of bottom node BMC to locate and dislocate NVMe. 5. Fixed multiple vulnerabilities with Supermicro BMC Virtual Media. 6. Display long AD domain names. 7. Fixed malfunction of IPMICFG –uniquepwd and -verifypwd commands.