

# IPMI Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X11SCW-F</b>  |
| <b>Release Version</b>  | <b>3.76.09</b>   |
| <b>Release Date</b>     | <b>2/12/2020</b>   |
| <b>Previous Version</b> | <b>3.76.01</b>   |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <ol style="list-style-type: none"><li>1. Set copyright to 2020.</li><li>2. Improved the dump speed of system troubleshooting.</li><li>3. Updated Jarsigner certificate.</li></ol>  |
| <b>New features</b>     | <ol style="list-style-type: none"><li>1. Added support for Java KVM text copy and paste feature.</li><li>2. Set BMC to store factory default option in flash.</li></ol>  |
| <b>Fixes</b>            | <ol style="list-style-type: none"><li>1. Fixed problem of SNMP losing some sensor information.</li><li>2. Fixed failure to update BIOS built in 2020.</li><li>3. Fixed failure to restore https port when restoring IPMI configuration.</li><li>4. Fixed mismatch of IPMI WebUI Fan Mode Help description.</li><li>5. Fixed inability to add IPv6 address.</li><li>6. Fixed absence of event if NTP is enabled and NTP server is not accessed.</li></ol> |

- |  |   |
|--|---|
|  | <p><b>7. Set System troubleshooting to support download of Version.txt, Health event log, Maintenance event log, FRU, and SMBIOS information.</b></p> <p><b>8. Fixed problem with CD-ROM image ISO mount with SUM.</b></p> <p><b>9. Fixed issues with CD-ROM image and support for special characters in config username.</b></p> <p><b>10. Fixed failure to release IKVM resource.</b></p> <p><b>11. Fixed inability of some nodes to detect BMC IP Gateway at SYS-F619P2-FT-DTP1-TS29T (MBD: X11DPFF-SN).</b></p> <p><b>12. Fixed inability of existing user to modify username on web page.</b></p> <p><b>13. Fixed malfunction of WebGUI display when hostname is too long.</b></p> |
|--|---|