

## IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X11DPU-V</b>  |
| <b>Release Version</b>  | <b>1.71.17</b>   |
| <b>Release Date</b>     | <b>12/30/2019</b>  |
| <b>Previous Version</b> | <b>1.71.12</b>   |
| <b>Update Category</b>  | <b>Critical</b>  |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <b>None</b>  |
| <b>New features</b>     | <b>1. BMC FW solution to program and store unique pre-programmed password.</b>   |
| <b>Fixes</b>            | <b>1. Fix Security fix.<br/>2. Verify the concatenate string of unique password is wrong<br/>3. [102893] Standard -- 9165 -- 1.71.8 --Unique Password can be clear using Raw Command 0x30 0x74 0x2.<br/>4. [102871] The unique password set bit can be removed by ipmitool raw command<br/>5. [102824] Standard -- 9165 -- 1.71.8-- Incorrect response 204 when post factory default with invalid option value on redfish<br/>[102823] Standard -- 9165 -- 1.71.8 -- Incorrect response 503 when post factory default with empty body on redfish</b> |

- |  |   |
|--|---|
|  | <ol style="list-style-type: none"><li>6. <b>[102894] [IPMI ECO] JAVA KVM should block Virtual Media section and give warning message when virtual media port was disabled</b></li><li>7. <b>[102710] IPMI fw 1.71.7 need new load factory default options for IPMICFG/SMCIPMITOOL/REDFISH</b></li><li>8. <b>[102657] Standard -- 9165 -- 1.71.7 -- inconsistent behavior for factory function</b></li><li>9. <b>[102544] Standard -- 9165 -- 1.71.7 -- incorrect message for Delete User Without Selecting Slot</b></li><li>10. <b>[101803] Fan speed will not back to optimal speed once full speed mode was set</b></li></ol> |
|--|---|