IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSW-iN/NT (All)	
Release Version	3.10.04	
Release Date	06/12/2020	
Previous Version	3.09.02	
Update Category	Critical	
Dependencies	N/A	
Important Notes	ECO #24243 IPMI Image SMT_H12AST2500_64M_31004_V.bin Please update IPMI with attached Flash Utility in package.	
Enhancements	 Add Kioxia NVMe SSD support. Support CX653106A via PLDM->MCTP->SMBUS. Modify the NVMe controller's API to apply the first and second generation CPLD register tables. Enhancement All platform support BRCM 3008 series. Support AMD GPU MISO. Modify the Redfish PATCH method at "/Systems/1/Bios" and "/Systems/1/Bios/SD" to allow updating of BIOS attributes. Update for NCSI 100G patch 	
New features	N/A	
Fixes	 Remove all fan running 40% under idle mode. Filter out abnormal values of VRM sensors especially 0xFF. DCMI power reading Improvement. Support x710 over PLDM->MCTP->SMBUS. Modify Fan speed limit. Fixes Some IPMI page display is abnormal with IE browser. Fixes [SMCIPMITools V2.23.x] got fail result via smstc (TC 131 ipmi oem x10cfg ddns) Fixes [SSM 3.2.x] IPMI security issue: Fail to login the hostname w/ "_" char via IPMIweb but it still can capture the screenshot via IPMIweb for the SSM/OS deployfail test 	

Product Manager	Date
First release.	
Revision 3.03 (2019/06/13)	
3. Fixes PBID# 103724 Redfish automation test fail. ; PBID# 104114 Redfish	h SATC failed
event	ter trigger thermal trip
2. Fixes PBID# 103796 Power on system onboard buzzer still beep when af	
2. Improved ADMIN password is incorrect after reloading IPMI configurati 1. Fixes PBID# 103696; smcipmitools V2.23.x; get fail output w/ command	
1. IPMI supports the commands required by SPM in the ROME CPU.	·
Rev. 3.09.02 (2019/12/16)	
D-11 2 00 02 (2040/42/4C)	