

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12DGO-6
Release Version	1.00.21
Build Date	12/18/2020
Previous Version	1.00.16
Update Category	Recommended
Dependencies	BIOS v1.0a
Important Notes	ECO #24681 IPMI image: SMT_H12AST2600_ROT_010021P.bin IPMI Update package: SMT_H12AST2600_ROT_010021P.zip
Enhancements	1. Added cold plate pump information for liquid cooling configuration.
New features	N/A
Fixes	1. Corrected LED status for dedicated LAN. 2. Fixed issue of ID 0xa0 appearing in Maintenance Event Log occasionally. 3. Fixed malfunction of Virtual Media CD-ROM mounting with IPv6. 4. Set inlet temperature sensor offset to reflect actual ambient temperature. 5. Fixed missing temperature reading for MLX card on IPMI. 6. Fixed issue of negative Inlet Temp reading appearing incorrectly in IPMI WebGUI. 7. Changed FPGA Temp parameter arg1 for FPGA version 2.A5 to follow newer specifications and prevent inability of IPMI to read the temperature of the FPGA.

Release Notes from Previous Release(s)

Revision 1.0 (2020/11/14)

First release.