

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X9SCA(-F)/X9SCi-LN4(F)
Release Version	2.3a
Release Date	1/6/2021
Build Date	1/6/2021
Previous Version	2.3
Update Category	Critical
Dependencies	None
Important Notes	None
Enhancements	1. Updated CPU microcode for SandyBridge/IvyBridge CPU.
New features	N/A
Fixes	1. Fixed problem of system hanging when entering setup with system date year 2021.

Release Notes from Previous Release(s)

2.3 (6/12/2018)

- 1. Updated CPU microcode to address 'Spectre' derivatives (CVE-2018-3639, CVE-2018-3640, and CVE-2017-5715) security issue.*
- 2. Changed BIOS revision to 2.3.*