

IPMI Firmware Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFF-AN6
Release Version	00.01.23
Build Date	01/08/2021
Previous Version	00.01.22
Update Category	Recommended
Dependencies	BIOS 1.0a (BIOS_H12SSFF-1C19_20201229_1.0a_STDsp)
Important Notes	IPMI Image: SMT_H12IPMI2600_00123_V.bin IPMI Update Package: SMT_H12IPMI2600_00123_V.zip
Enhancements	1. Added cache value for VRMSoc temperature sensor. 2. Modified voltage threshold UNC/LNC to UC/LC value. 3. Set a "failed" message to display in MEL when BMC/BIOS firmware update fails.
New features	N/A
Fixes	1. Fixed failure of CPLD JTAG to lock after finishing CPLD provision. 2. Fixed failure of UEFI SUM 1.1.0 to update CPLD, throwing out code 149. 3. Fixed missing bios_oem_fid file in restapi File.Export.

Release Notes from Previous Release(s)

00.01.22 (2020/12/30)

- 1. Fixed problem of BIOS halting at 0E during AC cycle.*
- 2. Fixed failure of SUM automation test.*
- 3. Prevented BMC reset due to NAND parsing.*
- 4. Fixed ability to add username with fewer than 4 characters.*
- 5. Fixed failure of SMSTC automation test.*
- 6. Changed display of BMC golden revision from 0.01.22 to 00.01.22.*
- 7. Added support for crash dump.*

00.01.20 (2020/12/15)

Initial Release