

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H12SSFF-AN6</b>
<b>Release Version</b>	<b>1.0b</b>
<b>Release Date</b>	<b>01/28/2021</b>
<b>Build Date</b>	<b>01/28/2021</b>
<b>Previous Version</b>	<b>1.a</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>IPMI firmware 00.01.25</b>
<b>Important Notes</b>	<b>BIOS Image: BIOS_H12SSFF-1C19_20210128_1.0b_STDsp.bin BIOS image and flash utility package: BIOS_H12SSFF-1C19_20210128_1.0b_STDsp.zip -</b>
<b>Enhancements</b>	<b>1. Set BMC to remove the reset from changing LAN data within the 30/20 command and BIOS to remove the patch.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>N/A</b>

***Release Notes from Previous Release(s)***

***1.0a (2020/12/19)***

1. Changed BIOS revision to 1.0a
2. Patched problem of POST randomly hanging at B2 during AC aging.
3. Corrected OEM FID VBIOS version.

***1.0 (2020/12/14)***

Initial release.