

# IPMI Firmware / BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>H12SSW-AN6 (All)</b>
<b>Release Version</b>	<b>1.00.23</b>
<b>Release Date</b>	<b>06/16/20201</b>
<b>Previous Version</b>	<b>1.00.20</b>
<b>Update Category</b>	<b>Critical</b>
<b>Dependencies</b>	<b>N/A</b>
<b>Important Notes</b>	<b>ECO #25516 BMC_H12AST2600-ROT-E201MS_20210617_01.00.23_STDsp.bin Please update IPMI with attached Flash Utility in package.</b>
<b>Enhancements</b>	Add Inlet Temp
<b>New features</b>	Support aspeed2600 chip A3
<b>Fixes</b>	1. Fixes when system power on, IPMI GUI power control status still show red. 2. [PB#126433] fixes the AOC location is not in sequence. 3. [PB#126783] There is BMC SEL "Dedicated LAN Link Down - Assertion" during AC cycle stress. 4. [PB#125637] fixes the IPMI web can not read AIOM NIC temperature 5. [PB#122813] fixes the sensor name "AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link 6. [PB#128391] fixes the AOC location info. (AOC-AG-i2M) is N/A Copy Project Issue Link 7. [PB#128412] fixes the Marvell controller (AOC-SLG2-2TM2) info and function are invalid in BMC WEB

**Release Notes from Previous Release(s)** – these will be appended at the bottom of the current release notes in italic and in smaller print

*1.00.20 (5/12/2021)*

*First release.*