

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSFR-AN6
Release Version	01.00.23
Release Date	7/12/2021
Previous Version	01.00.08
Update Category	Recommended
Dependencies	N/A
Important Notes	IPMI Image: BMC_H12AST2600-ROT-E201MS_20210712_01.00.23_STDsp.bin IPMI Update Package: BMC_H12AST2600-ROT-E201MS_20210712_01.00.23_STDsp.zip
Enhancements	N/A
New features	Support aspeed2600 chip A3
Fixes	<ol style="list-style-type: none">1. The Marvell controller(AOC-SLG2-2TM2) info and function are invalid in BMC WEB. Copy Project Issue Link2. The AOC location info(AOC-AG-i2M) is N/A Copy Project Issue Link3. The AOC location is not in sequence. Copy Project Issue Link4. The sensor name"AIOM" under tab "Network AOC" is different from tab "Sensor" Copy Project Issue Link5. Opening and closing the HTML5 Remote Console Disables Remote Console

Release Notes from Previous Release(s)

01.00.08 (1/28/2021) 1. Digital Battery Reading Check Fail 2. No AIOM sensor reading on IPMI GUI. 01.00.00 First release.
