

## BMC Firmware Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X10DRT-PS</b>
<b>Release Version</b>	<b>3.93</b>
<b>Build Date</b>	<b>5/28/2021</b>
<b>Previous Version</b>	<b>3.89</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>1. BIOS upload timeout set to 30 min if web session timeout is 0 and 5 minutes if session timeout &gt; 0 and &lt; 5 minutes.</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<b>1. Correct sorting on Sensor Readings. 2. Properly verify OEM security BIOS firmware. 3. Corrected SMCIPMITool via SMSTC. 5. Disallow local BMC Password greater than 19 characters. 6. Corrected behavior when switching to other languages on webpage. 7. Corrected destination address after updating firmware by SMCIPMITool.</b>