

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |  |
|-------------------------|--|
| <b>Product Name</b>     | <b>X12DPG-QR</b>   |
| <b>Release Version</b>  | <b>1.0a SPS 4.4.4.58</b>   |
| <b>Build Date</b>       | <b>12/03/2021</b>  |
| <b>Previous Version</b> | <b>1.0 (Beta release)</b>  |
| <b>Update Category</b>  | <b>Recommended</b>   |
| <b>Dependencies</b>     | <b>None</b>  |
| <b>Important Notes</b>  | <b>None</b>  |
| <b>Enhancements</b>     | <b>None</b>  |
| <b>New features</b>     | <b>None</b>  |
| <b>Fixes</b>            | <ol style="list-style-type: none"> <li>1. Updated the Intel BKC to 2021_WW39 (KIT #653811), RC, Intel update BKC to fix general platform issues. RC is updated to 21.P41</li> <li>2. Updated the Intel BKC to 2021_WW39 (KIT #653811), SPS, Intel update BKC to fix general platform issues. SPS is updated to 4.4.4.58</li> <li>3. Updated the Intel BKC to 2021_WW39 (KIT #653811), ACM, Intel update BKC to fix general platform issues. ACM is updated to 1.0.Dh.</li> <li>4. Updated the Intel BKC to 2021_WW39 (KIT #653811), SINIT, Intel update BKC to fix general platform issues. SINIT is updated to 1.0.Fh.</li> <li>5. Updated the Intel BKC to 2021_WW39 (KIT #653811), CPU 606A6 Microcode, Intel update BKC to fix general platform issues. CPU 606A6 Microcode is updated to 0D000311.</li> <li>6. Updated the Intel BKC to 2021_WW39 (KIT #653811), Intel VROC UEFI, Intel update BKC to fix general platform issues. Intel VROC UEFI is updated to 7.6.0.1012.</li> <li>7. Updated the Option ROM for Intel 10G PXE, Option ROM is updated to address issues. Intel 10G PXE is updated to 2.2.05.</li> <li>8. Updated the Option ROM for Intel 10G UEFI Driver, Option ROM is updated to address issues. Intel 10G UEFI Driver is updated to 4.9.10.</li> </ol> |