

## IPMI Release Notes

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X12SPW-(T)F</b>
<b>Release Version</b>	<b>01.01.17</b>
<b>Build Date</b>	<b>3/4/2022</b>
<b>Previous Version</b>	<b>01.00.21</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<b>None</b>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<p><b>Fixed the following issues:</b></p> <ol style="list-style-type: none"><li><b>1. Add option in BMC UI to create disabled user or edit user to disable.</b></li><li><b>2. Storage feature broken in 01.01.10.</b></li><li><b>3. Specific strings could brute force the BMC directory.</b></li><li><b>4. IPMITool can set LAN mode out of range.</b></li><li><b>5. Need to grey out "Create Raid" icon if no more physical drives available to create new Raid volume.</b></li><li><b>6. Can't sync NTP server when BMC has an IPv6 DNS.</b></li><li><b>7. Password does not accept a backslash “\”.</b></li><li><b>8. XSS attack at Notification Alert Redfish protocol.</b></li></ol>

	<ul style="list-style-type: none"> <li>9. Support Preserve BIOS Boot Options Configuration when updating BIOS FW.</li> <li>10. BMC should maintain fan speed during fwUP, and BMC reset.</li> <li>11. Set maximum number of SEL up to 4096.</li> <li>12. Chosen file is blocked over the area at License Activation page.</li> <li>13. BIOS update failure.</li> <li>14. All Broadcom AOC controllers such as 3008, 3616, 38xx and 39xx are not discoverable.</li> <li>15. Unspecified Event Log Assertion when AC ON.</li> <li>16. iKVM(JAVA plug-in/HTML5) should support IMA file type.</li> <li>17. Add SNMP type user does not have and asterisk * to alert that Auth Key and Private Key are required items.</li> <li>18. Language Change title string is not translated.</li> <li>19. Improve PSU initialization code, add delay and retries.</li> <li>20. "Delete" icon should not appear while logged in as "Operator" or "User" privileges account.</li> <li>21. Redfish API Automation test failure.</li> <li>22. Mount failed pop up error message and Even log are incorrect.</li> <li>23. Mount *.img displays wrong file type on Java iKVM Virtual Media.</li> <li>24. Update invalid FW will show MEL message when updating BIOS and CPLD.</li> </ul>
--	-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------