

BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DAi-N6
Release Version	1.2 SPS: 4.4.4.62
Build Date	02/07/2022
Previous Version	1.1b
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	1. Updated Intel BKC to 2021_WW52 (KIT #709738), RC 2. Updated Intel BKC to 2021_WW52 (KIT #709738), SPS 3. Updated Intel BKC to 2021_WW52 (KIT #709738), ACM 4. Updated Intel BKC to 2021_WW52 (KIT #709738), SINIT 5. Updated Intel BKC to 2021_WW52 (KIT #709738), CPU 606A6 Microcode 6. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel VROC UEFI 7. Updated Intel BKC to 2021_WW52 (KIT #709738), Intel PMEM UEFI 8. Updated Option ROM for Intel I210 Giga LAN UEFI
New features	N/A
Fixes	N/A

Release Notes from Previous Release(s)

1.1b (9/10/2021)

1. Updated Intel BKC to 2021_WW32 (KIT #645801), RC.
2. Updated Intel BKC to 2021_WW32 (KIT #645801), SPS.
3. Updated Intel BKC to 2021_WW32 (KIT #645801), ACM.
4. Updated Intel BKC to 2021_WW32 (KIT #645801), SINIT.
5. Updated Intel BKC to 2021_WW32 (KIT #645801), CPU 606A6 Microcode.

1.1a (8/9/2021)

1. Updated Intel BKC to 2021_WW24 (KIT #642595), RC.
2. Updated Intel BKC to 2021_WW24 (KIT #642595), SPS.
3. Updated Intel BKC to 2021_WW24 (KIT #642595), ACM.
4. Updated Intel BKC to 2021_WW24 (KIT #642595), SINIT.
5. Updated Intel BKC to 2021_WW24 (KIT #642595), CPU 606A6 Microcode.
6. Added SMC DIMM bar code information to SMBIOS type 17 serial number field.
7. Fixed failure of AC on/off test in some conditions.

1.1 (4/30/2021)

1. Updated Intel BKC to WW17'21 (PV), RC.
2. Updated Intel BKC to WW17'21 (PV), SPS.
3. Updated Intel BKC to WW17'21 (PV), 606A4 Microcode.
4. Updated Intel BKC to WW17'21 (PV), 606A5 Microcode.
5. Updated Intel BKC to WW17'21 (PV), 606A6 Microcode.
6. Updated Intel BKC to WW17'21 (PV), BIOS ACM.
7. Updated Intel BKC to WW17'21 (PV), SINIT ACM.
8. Updated Intel BKC to WW17'21 (PV), NVDIMM UEFI HII.
9. Updated Intel BKC to WW17'21 (PV), VMD VROC.

1.0a (3/18/2021)

1. Updated Intel BKC to WW11'21.