

## BIOS Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

|                         |                               |
|-------------------------|-------------------------------|
| <b>Product Name</b>     | <b>X12DAi-N6</b>              |
| <b>Release Version</b>  | <b>1.2b SPS: 4.4.4.62</b>     |
| <b>Build Date</b>       | <b>6/1/2022</b>               |
| <b>Previous Version</b> | <b>1.2a</b>                   |
| <b>Update Category</b>  | <b>Recommended</b>            |
| <b>Dependencies</b>     | <b>None</b>                   |
| <b>Important Notes</b>  | <b>None</b>                   |
| <b>Enhancements</b>     | <b>None</b>                   |
| <b>New features</b>     | <b>None</b>                   |
| <b>Fixes</b>            | <b>1. FRU Test Case - 113</b> |

**Release Notes from Previous Release(s)**

**1.2a (4/19/2022)**

1. Rolled back VROC SATA/sSATA EFI driver to VROC PreOS v7.6.0.1012. This fixes a system hang when VMD is enabled.

**1.2 (2/07/2022)**

1. Updated Intel BKC to 2021\_WW52 (KIT #709738), RC
2. Updated Intel BKC to 2021\_WW52 (KIT #709738), SPS
3. Updated Intel BKC to 2021\_WW52 (KIT #709738), ACM
4. Updated Intel BKC to 2021\_WW52 (KIT #709738), SINIT
5. Updated Intel BKC to 2021\_WW52 (KIT #709738), CPU 606A6 Microcode
6. Updated Intel BKC to 2021\_WW52 (KIT #709738), Intel VROC UEFI
7. Updated Intel BKC to 2021\_WW52 (KIT #709738), Intel PMEM UEFI
8. Updated Option ROM for Intel I210 Giga LAN UEFI

**1.1b (9/10/2021)**

1. Updated Intel BKC to 2021\_WW32 (KIT #645801), RC.
2. Updated Intel BKC to 2021\_WW32 (KIT #645801), SPS.
3. Updated Intel BKC to 2021\_WW32 (KIT #645801), ACM.
4. Updated Intel BKC to 2021\_WW32 (KIT #645801), SINIT.
5. Updated Intel BKC to 2021\_WW32 (KIT #645801), CPU 606A6 Microcode.

**1.1a (8/9/2021)**

1. Updated Intel BKC to 2021\_WW24 (KIT #642595), RC.
2. Updated Intel BKC to 2021\_WW24 (KIT #642595), SPS.
3. Updated Intel BKC to 2021\_WW24 (KIT #642595), ACM.
4. Updated Intel BKC to 2021\_WW24 (KIT #642595), SINIT.
5. Updated Intel BKC to 2021\_WW24 (KIT #642595), CPU 606A6 Microcode.
6. Added SMC DIMM bar code information to SMBIOS type 17 serial number field.
7. Fixed failure of AC on/off test in some conditions.

**1.1 (4/30/2021)**

1. Updated Intel BKC to WW17'21 (PV), RC.
2. Updated Intel BKC to WW17'21 (PV), SPS.
3. Updated Intel BKC to WW17'21 (PV), 606A4 Microcode.
4. Updated Intel BKC to WW17'21 (PV), 606A5 Microcode.
5. Updated Intel BKC to WW17'21 (PV), 606A6 Microcode.
6. Updated Intel BKC to WW17'21 (PV), BIOS ACM.
7. Updated Intel BKC to WW17'21 (PV), SINIT ACM.
8. Updated Intel BKC to WW17'21 (PV), NVDIMM UEFI HII.

9. Updated Intel BKC to WW17'21 (PV), VMD VROC.

**1.0a (3/18/2021)**

1. Updated Intel BKC to WW11'21.