IPMI Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12DPT-B6
Release Version	01.02.35
Build Date	
Previous Version	7/08/2022 01.02.19
Update Category	Recommended
Opuale calegory	Recommended
Dependencies	None
Important Notes	None
Enhancements	 Added support for the AIOM AOC-ATG-B2TM Added support for Intel GPU ATS M1 and ATS M3 Added Enhanced Smart Power (new UI) Error Message Display Behaviors and MELs were added Updated iKVM with New UI. Added support for IPMI LAN disable Added NIC link up/down event
New features	None
Fixes	 Fixed: AOC-AG-i4M the i350 does not support sensor but the WEB UI show sensor status. Fixed: Redfish automation test failed w/ 8 failures on v01.02.23 Fixed: Automation tests Failure [140340] - Redfish automation test failed w/ 8 failures on v01.02.23 [139728] - IPMI ECO

	automation test failed. [140170] - Ignore query string if it's longer
	than 128 bytes
4.	Fixed: Time zone not reset to default after disabling NTP through
	redfish
5.	Fixed: Redfish automation test failure.
6.	Fixed: Ignore question mark if no query parameter is appended
	to Redfish URI [137739] - IPMICFGECO failed on TC122. [138143] -
	SUMECO failed on TC373
7.	Fixed: CPLD version display is not matched between existing
	version and new version on Update CPLD Step 3
8.	Fixed: no sensor reading for AOC-SMG3-2M2-B
9.	Fixed: Redfish automation test failure. There are 10 failure items
	when running SATC test.
10	D. Fixed: "Export to Excel" button is not deactivated when all
	Maintenance Event Log categories are deselected.
11	L. Fixed: Multi Node page failure
12	2. Fixed: Special Characters Allowed in SNMPv2 Community String
13	3. Fixed: WEBUI wrongly did not allow to edit user properties in FW
	1.00.00
14	1. Fixed: remove license key check in system troubleshooting Web
	GUI page.
15	5. Fixed: The LED blinking action is too slow
16	5. Fixed: Login screen should be support "eye-icon" button to view
	password.
17	7. Fixed: IPMI Web - Network page "DHCPv6" check fail
18	3. Fixed automation test failure, test case 408: BMCWebUI