IPMI Firmware Release Notes

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	X12SPT-PT
Release Version	01.02.42
Build Date	08/25/2022
Previous Version	01.02.33
Update Category	Recommended
Dependencies	None
Important Notes	None
Enhancements	N/A
New features	1. Added support for the AOC-STGC-i2T
Fixes	Removed license key check in system troubleshooting WEBGUI page.
	2. Fixed LED blinking, it was taking too long a time
	3. Added Error Message Display Behaviors and MELs
	4. Fixed incorrect error msg when disabling as session user.
	5. Fixed issue where the IPMI LAN VLAN value is not expected.
	VLAN ID value is not matching with spec.

- Fixed where HTML5/Java iKVM is showing the wrong message when updating IPMI firmware in old/new UI iKVM. Protocol won't disconnect when updating IPMI.
- 7. Fixed: GUI -- Display icon color is incorrect when mounting successfully
- 8. Fixed: VROC info does not show in Redfish
- Fixed: Virtual keyboard language won't sync with iKVM language.
- 10. Fixed: Login screen should support "eye-icon" button to view password.
- 11. Fixed IPMI Web Network page "DHCPv6" check failure
- 12. Added warning message for RAID HDD type mixing.
- 13. Fixed: SMTP User Name now supports @ and .
- 14. Fixed: IPMI sensor reading "AOC_NIC1 Temp" issue with AOC-E810-XXVDA4L-RI012(M10767-007)
- 15. Fixed: configuration backward compatibility issue in 01.02.40
- 16. Fixed: IPMI automation test failure