

IPMI Firmware / BIOS Release Notes Form

Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.

Product Name	H12SSG-ANP6
Release Version	00.01.06
Release Date	3/16/2022
Previous Version	00.01.04
Update Category	First Release
Dependencies	BIOS R 2.4
Important Notes	IPMI Image: BMC_H12SSG-AN6-AST2600-ROT1PLUS-9301MS_20220316_00.01.06_STDsp.bin IPMI Update Package: BMC_H12SSG-AN6-AST2600-ROT1PLUS-9301MS_20220316_00.01.06_STDsp.bin.ZIP
Enhancements	N/A
New features	N/A
Fixes	<p>Fixed the following issues:</p> <ol style="list-style-type: none">1. U.2 sensor lost during cburn on and off test.2. Can't launch iKVM via JAVA.3. ROT would wrongly trigger BIOS recovery when AC ON.4. LCMC information will disappear and fan function abnormal after reboot.

Release Notes from Previous Release(s)

00.01.04 (12/17/2021)

Initial Release