

## BMC Firmware Release Notes Form

*Supermicro disclaims all express and implied warranties, including without limitation, the implied warranties of merchantability, fitness for a particular purpose, and non-infringement, as well as any warranty arising from course of performance, course of dealing, or usage in trade. All products, computer systems, dates, and figures specified are preliminary based on current expectations, and are subject to change without notice. Supermicro and the Supermicro logo are trademarks of Super Micro Computer, Inc. in the U.S. and/or other countries. Copyright © 2018 Super Micro Computer, Inc. All rights reserved.*

<b>Product Name</b>	<b>X13DET-B</b>
<b>Release Version</b>	<b>1.00.12</b>
<b>Build Date</b>	<b>08/30/2022</b>
<b>Previous Version</b>	<b>N/A</b>
<b>Update Category</b>	<b>Recommended</b>
<b>Dependencies</b>	<b>None</b>
<b>Important Notes</b>	<b>None</b>
<b>Enhancements</b>	<ol style="list-style-type: none"><li>1. IPMI upload config message has been changed</li><li>2. Added support for Marvel card SCC-A2NM2241G3-B1</li><li>3. Removed license key check in system troubleshooting WEBGUI page</li><li>4. Error Message Display Behaviors and MELs were added</li><li>5. Fixed AOC Temp Sensors that is out of order.</li><li>6. Removed System NIC (Systemslot, port) event description</li><li>7. Fixed: Uploaded correct bin type should not return "Invalid file type!" message</li></ol>
<b>New features</b>	<b>N/A</b>
<b>Fixes</b>	<ol style="list-style-type: none"><li>1. Fixed the NTP setting that is not syncing after BMC reboot, when setting invalid NTP server.</li><li>2. Fixed: X13DET-B/SCC-A2NM2241G cannot read VPD</li><li>3. Fixed the LED blinking that is too slow</li><li>4. Fixed "Hostname" field, which only supported a~z, A~Z and 0~9 chars at Network page.</li><li>5. Fixed the configuration backward compatible issue in 01.02.40</li><li>6. Fixed BPN CPLD update failure in 01.00.08</li></ol>